

VEHICLE INSPECTION REPORT

21411

STIGA PARK COMPACT 16

Non Runner
Inspection

Vehicle	
VAT	Plus VAT
V5	N/A

Details

Location	Doncaster	Fuel Type	Diesel	Gearbox	Hydrostatic
Reg. date		Colour		Axle Combi	4WD
Year	2007	VIN	070420071A		
Mileage	TBC	Body Style	Ride on Mower		

NO POWER

Tyres

NSF
NSR
OSF
OSR
Spare

Photos



